


Note: Poor site conditions can affect the stability of the structure. Consult a qualified professional engineer to determine site specific construction details.



RisiStone®
retaining wall systems

8500 Leslie Street, Suite 390
Thornhill, Ontario
Canada, L3T 7M8
Tel 905.882.5898 Fax 905.882.4556
<http://www.risistone.com>
©2002 Risi Stone Systems

Pisa 2®
Pond Cross Section

P21MDET003.DWG