


Note: Poor site conditions can affect the stability of the structure. Consult a qualified professional engineer to determine site specific construction details.



**RisiStone®**  
retaining wall systems

8500 Leslie Street, Suite 390  
Thornhill, Ontario  
Canada, L3T 7M8  
Tel 905.882.5898 Fax 905.882.4556  
<http://www.risistone.com>  
©2002 Risi Stone Systems

**RomanStack®**  
TREE RING

**RS1GDET001.DWG**